| Registration | Registration | Model | Chassis Number | Mileage |
|---|---|---|---|---|
| MX65 BPE | MX65 BPE | 570s Coupe SALES | SBM13DAC1G**W0002** | 23176 |
| Colour | Engine Code | Date Reg | Technician | Paint Code |
| White | | 07/01/2016 | RR | |

| Advisories |
|---|
| Wheel alignment advised **(Carry out wheel alignment - Cost of £330)** |
| Advise Front wheel balance **(Carry wheel balance - Cost of £50)** |
| Advise bleed brakes **(Carry out brake fluid change - Cost of £168.04)** |
| £70 of fuel put in on road test |
| Oil too low (red) |
| Smart tag tracker under brake fluid cover cap |
| After market stickers applied |
| Brake fluid slightly dark - **(Carry out brake fluid change - Cost of £168.04)** |
| Both front tyre spoilers loose (Inner arch) **(Refit and secure - cost of £82.50)** |
| FR arch has slight corrosion **(Carry out corrosion repairs and paint - Cost of £1200)** |
| FL wheel heavily curbed **(Carry out refurbishment - Cost of £175)** |
| FR wheel has small chips |
| Tyres slightly wearing on the edges (all) |
| Front upper arm bushes both cracking - no play |
| Both front lift banjo bolts rusty |
| Small chips on passenger door |
| Front floor scuffs/scrapes |
| FL lower arm rear bush slight cracking - no play |
| Both front track rods slight rusty |
| Both front drop links rusty |
| Brake unions starting to rust |
| Greasy residue on clutch filter housing |
| Missing both middle datum plugs |
| LH manifold heatshield tab broken **(Remove left manifold, repair and refit - Cost of £1952.31)** |
| LH driveshaft has slight greasiness |

| |
|---|
| RR lower rear bush starting to crack - no play |
| Slight rusty RR spring (bottom) |
| Rear brake unions starting to rust |
| RR drop link  dust boot slipped from mount **(Replace rear right drop link - Cost of £139.04)** |

| |
|---|
| LH main coolant pipe slight chafing on other coolant pipe **(Remove and apply protection to pipes - Cost of £82.50)** |
| Both main coolant pipe slight chafing on chassis **(As Above)** |
| 10th service due - clutch oil not been done **(10th service Inc Clutch oil and filter - Cost of £1926.36)** |
| No PPF on front arches |
| Rear tyres 3.4mm at lowest |
| Only 1 key with vehicle **(Supply and code 2nd Key - Cost of £644.90)** |