| Registration | Registration | Model | Chassis Number | Mileage |
|---|---|---|---|---|
| BX68 ATV | BX68 ATV | 570 Spider SALES CAR | SBM13FAC2K**W00613** | 34546 |
| Colour | Engine Code | Date Reg | Technician | Paint Code |
| BLACK | | 27/09/2018 | | |

| Advisories |
|---|
| Squeaks and clunks from roof seal |
| AC not cold **(Inspect & check ac system, Advise on repair cost - Cost of £330)** |
| Seat bolsters un clipped **(secure seat bolsters - Cost of £82.50)** |
| Wind noise from drivers window |
| Vehicle paint work condition to be checked after valeting - additional polishing may be needed |
| Passenger door hinge cracked **(Replace passenger door hinge - £1950.38)** |
| Old glue residue under bonnet lip |
| Corrosion FR arch, FL arch, passenger door inner, Drivers door outer & inner, RR arch**(corrosion repairs & Paint - Cost of** |
| **(PPF cost for repaired panels - Cost of £1,404.00)** |
| 570s badges missing on skirts **(Fit door skirt badges £269.14)** |
| Dry coolant residue LH LTR- not currently leaking |
| FR disk has small chip on face |
| FR upper forward bushes split **(Replace front right upper arm - Cost of £671.65)** |
| FL upper forward bushes slight cracking |
| Front floor scuff and scrapes |
| Both front upper ball joint boots un seated - Ball joint clips rusty **(Replace front left upper ball joint boot - Cost of £198.32)** |
| Both front track rods and drop links rusty |
| Lift Banjo bolts rusty |
| Both front lower forward bushes split on external rubber, main bush okay |
| FL shock leaking **(replace front left shock - Cost of £1325.83)** |
| Flexi brakes hoses starting to rust **(clean up brake hoses and apply ACF50 - Cost of £82.50)** |
| Old coolant residue on water pump |
| All engine mounts have slight play |
| LH manifold tab cracked **(Remove left manifold, repair and refit - Cost of £1952.31)** |
| RL spring rusty at bottom |