Registration	Registration	Model	Chassis Number	Mileage
AA12 CCC	AA12 CCC	12c coupe	SBM11AAC6CW00114	16504
Colour	Engine Code	Date Reg	Technician	Paint Code
White		26/04/2012		

Advisories
Wheel alignment advised **(Carry out wheel alignment - Cost of £330)**
Washers not working/ pressure poor **(Repair screen washers - Cost of £165)**
Multiple patches of under bonnet corrosion **(Carry out corrosion repairs and paint under bonnet - Cost of £900)**
Wiper arm corrosion
Mould in both headlights
Sunstrip fitted
Paint lift/ imperfections on both intake areas
Roof wrapped
RR reflector slightly loose/insecure **(Secure reflector - Cost of £82.50)**
Corrosion on LH airbrake ram mount
PPF lift on both front arches
Road rash behind all wheels
Scuffs and scrapes to front bumper underside **(Repair and paint lower section of bumper - Cost of £750)**
Front floor damaged **(Replace front floor - Cost of £1356.45)**
Guide vein broken
Diffuser poorly wrapped
PPF bubbling and coming off on front bumper
Scuff on LH skirt
FR door seal trim hanging down **(Secure door seal - Cost of £82.50)**
LH indicator on mirror slightly loose
PPF lifting on front arches
Scuff on RH mirror cap
Tyre spoilers/fixings missing
Oil tank sump bung greasy
FR spring rusty at bottom and top **(Replace both springs - Cost of £807.50)**

FL PSF line oily residue
LH main coolant pipe chafing on another pipe **(Adjust and apply protection - Cost of £82.50)**
FL datum plug missing **(Fit datum plug - Cost of £6.94)**

Dirty/greasy residue on RR shock - looks very old - no change from last time
All engine mounts squeaking
RL spring rust bubbling under paint