Registration	Registration	Model	Chassis Number	Mileage
WX66 HBJ	WX66 HBJ	570s SALES CAR	SBM13DAC7H**W0013**	26845
Colour	Engine Code	Date Reg	Technician	Paint Code
White		27/09/2016		

Advisories
Slight noise front front brakes - will monitor
Slight squeak FL suspension
Buzzing RL 3-3.5k RPM - no manifold issue found
FL tyre pressure was at 39.9 (re set)
Non MC front tyres
FL wheel damage **(Wheel refurb - Cost of £175)**
Front floor scuffed and cracked - still structural
Discs matted - still all okay
FL upper arm bushes cracking - this would be causing the squeak noted **(Replace front left upper arm - Cost of £643.12)**
Front brake lines corroded **(Replace both front brake flexi pipes - Cost of £616.02)**
Slight residue on LTR pipes - minor
Centre engine mount has play **(Replace horizontal engine mount - Cost of £351.79)**
Rear brake hoses slight corrosion