Registration	Registration	Model	Chassis Number	Mileage
MX62 FVP	MX62 FVP	12c coupe SALES CAR	SBM11AAC8C**W00151**	27681
Colour	Engine Code	Date Reg	Technician	Paint Code
Red				

Advisories
Wheel alignment advised, steering wheel off centre **(Carry out wheel alignment - Cost of £330)**
AC not cold (tested and on 4 bar pressure - advise regas) **(Carry out AC service - Cost of £135)**
Front wheels vibration **(Balance front wheels - Cost of £50)**
Slight Condensation air brake light
Drivers door leading edge paint chipped
1 out of 3 screen washers blocked **(Unblock and clear washer jets - Cost of £82.50)**
Drivers seat missing buttons **(Replace drivers seat switch pack - Cost of £655.82)**
FL lower bushes split **(Replace front left lower arm - Cost of £1847.49)**
General scrapes and scuffs on front floor
Guide vanes both broken
Gearbox has very old greasy residue on it
Main coolant pipes has old coolant residue - looks to be from an old leak
Engine mounts have slight play
Brake discs holes blocked
Rear track rods rusty
Replace lower bushes cracking - no play
RR shock wet/damp at the bottom **(Replace rear right shock - Cost of £1159.16)**
FL door/arch seal hanging down **(Repair - Cost of £82.50)**
Park brake pads crumbling **(Replace park brake pads - Cost of £393.56)**
Drive shaft rusty LH side
No tyre spoilers fitted
Upper oil pipe braid cracked **(Replace upper oil pipe - Cost of £450.70)**
RH heat shield bolts missing **(Fit missing bolts - Cost of £82.50)**