Registration	Registration	Model	Chassis Number	Mileage
BX18 EOE	BX18 EOE	570GT SALES CAR	sbm13gac1j**w004836**	31857
Colour	Engine Code	Date Reg	Technician	Paint Code
Orange				

Advisories
Wheel alignment advised **(Carry out wheel alignment - Cost of £330)**
Ac not cold - 2.4 bar pressure **(Carry out investigation into AC system - Cost of £330)**
Front left knock on bumps
Corrosion On rear left arch & 1/4 near cant rail **(Carry out corrosion repair and paint - Cost of £1200, Plus PPF of**
Corrosion on rear right arch & 1/4 near cant rail **(Carry out corrosion repair and paint - Cost of £1200, Plus PPF of**
Corrosion under bonnet + PPF bubble **(Carry out corrosion repair and paint - Cost of £900, Plus PPF of £513.50)**
Corrosion starting on both front arches **(Carry out corrosion repairs and paint to both Arches - Cost of £2400, Plus**
Corrosion on drivers door outer **(Carry out corrosion repair and paint - Cost of £1200, Plus PPF of £245)**
Minor damage RR alloy
Both door hinges cracked **(Replace both door hinges - Cost of £3900.76)**
PPF bubble left door upper
RR side bezel loose (squeaking) **(Repair Rear right bezel - Cost of £82.50)**
Drivers side door 570GT badge missing the 7 **(Replace 570GT side badge - Cost of £134.57)**
Drivers window trim loose & corroded
Damage to front right wheel and tyre rim protector
Cosmetic damage (curb rash/chips) to wheels
PPF bubble FL door
FR upper forward bush cracked
Front floor & splitter - scuffs and scrapes
FL brake duct missing zip tie
Dry/old residue on FR LTR pipe
All front lower bushes cracking
FL shock leaking - **(Replacement under TMS warranty)**
All brake unions starting to rust
Rear lower rear bushes cracking

Rear upper forward bush cracking very slightly
Play in all engine mounts
LH manifold tab cracked **(Remove left manifold, repair and refit - Cost of £2282.31)**

Tyre depth low - 2.5mm at lowest **(Replace rear tyres - Cost of £670)**
RH rear exhaust heat shield rattle **(Repair rear exhaust link pipe heat shield - Cost of £165)**