Registration	Registration	Model	Chassis Number	Mileage
W7 LKR	W7 LKR	570GT SALES CAR	SBM13GACXH**W0032**	23901
Colour	Engine Code	Date Reg	Technician	Paint Code
Grey		03/05/2017	RR	

Advisories
1 key not working (**Supply and code new key - Cost of £683.84**)
LH door hinge cracked **(Replace Door hinge - Cost of £1950.38)**
RH tyre spoiler loose
Corrosion under bonnet **(warranty covering work)**
Corrosion on FR arch **(warranty covering work)**
Corrosion on passenger door **(warranty covering work)**
Corrosion inside drivers door **(Repair and paint - Cost of £1200)**
Rear tyre tread getting low 2.8mm at lowest **(Replace rear tyres - Cost of £660)**
Both cheater panel trims lifted/loose **(Secure both panels - Cost of £82.50)**
Paint on FR wheel
Front floor scuffed/scraped
Greasy residue on Front left shock - clean and monitor - if it returns replacement will be needed
Rear lower arm rear bush slight cracking
Slight play in engine mounts
Dried coolant residue on Y piece **(Replace clip on water pump LTR pipe - Cost of 82.50)**