THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570S-Coupe	SBM13DAC1GW000227	

Pre road test		Notes / rectification
Photograph vehicle condition	☑	
Photograph interior	☑	
Check Bodywork for Damage	☑	
Check closures & hinges & bonnet emergency cable	☑	
Check glazing Inc Glass Roof	☑	
Check luggage compartment	☑	
Charger with vehicle?	☑	

Notes:
Tracker fitted under brake fluid cap in front luggage area
After market stickers applied
FR arch has slight corrosion
Small chips on passenger door

Road test		Notes / rectification
Check all drive modes	☑	
Check Seat Belt Operation	☑	
Check Seat Functions	☑	
Check Operation of Controls and Switches & iris	☑	
Check Hand Brake and Foot Brake Travel	☒	Advise brake bleed
Check Hvac operation	☑	
Radio working?	☑	
Check Warning Lamp Indicators	☑	
Check washers/wipers & horn	☑	
Oil level:	OK	
Check TPMS	☑	
Battery %	100	
Check mirror functions	☑	
Check exterior lighting	☑	
Check park brake function	☑	
Advise on wheel alignment feel	☒	Advise wheel alignment, Advise front wheel balance

Notes:

Workshop		Notes / rectification
Check Power steering fluid	☑	
Check brake fluid	☒	Brake fluid slightly dark, advise replace
Check engine bay	☑	
Check for Bodywork Corrosion	☒	See pre road test notes
Check front lights & reflectors	☑	
Check rear lights & reflectors	☑	

THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570S-Coupe	SBM13DAC1GW000227	

Vehicle on lift (half height)		Notes / rectification
Check Tyre Tread & condition	☒	All tyres slightly wearing on edges

Measurement	NSF	OSF	NSR	OSR
Pads (mm)	8.2mm	7.7mm	9.3mm	9.2mm
Discs (mm)				
Tyre Depth	5.9/6.6/6mm	5.4/6.3/5.7mm	4.7/3.2/3.4mm	4.3/3.7/3.8mm
Tyre pressure	28.4psi	29.7psi	30.8psi	31psi
Tyre Age	2024	2022	2021	2021

Turn front wheels & check Upper arms/suspension	☒	Front upper arm forward bushes both cracking, FR upper arm rear bush slight cracking
Check Front Brakes	☒	Front discs have slight roughness, advise remove and weigh
Check Rim Condition	☒	FL wheel heavily curbed, FR wheel has small chips
Check Rear Brakes	☑	
Check Park brake Pads	☑	

Vehicle on lift (full height)		Notes / rectification
Check Front Floor & Tyre spoilers	☒	Both front tyre spoilers loose, Front floor has scuffs/scrapes
Check guide vanes	☑	
Check brake ducts	☒	Both front brake ducts missing fixings
Check LTR pipes	☑	
Check Front Suspension Ball joints & bushes	☒	FL lower arm rear bush slight cracking
Check Steering Joints/Bushes/Gaitors	☒	Both front track rods slightly rusty, both front drop links rusty
Check Front shocks & Springs	☒	Both front shock lift banjo bolts rusty.
Check Front Flexible Brake Hoses	☒	Front brake unions are starting to rust
Check for leaks - oil systems	☑	
Check gearbox for leaks	☒	Greasy residue on clutch filter housing
Check cooling systems for leaks	☒	Dried coolant residue around front case, LH main coolant pipe slightly chafing on separate pipe, both main coolant pipes slight chafing on chassis
Check engine mounts	☑	
Check manifolds	☒	LH exhaust manifold heatshield tab broken
Check Vacuum pipes	☑	
Check Drive Shafts & seals	☑	LH driveshaft has slight greasiness
Check rear suspension ball Joints & Bushes	☒	RR lower arm rear bush starting to crack
Check Rear shocks & Springs	☑	RR spring slightly rusty at base
Check Rear brake ducts	☑	
Check Rear Flexible Brake Hoses	☒	Rear brake unions starting to rust
Check bar links & Link rods	☒	RR drop link dust boot slipped from mount
Check radiators	☑	
Under side damage	☒	Missing both middle datum plugs missing

Notes:
10th service due, clutch oil hasn't been done
No PPF on front arches