THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570S-Spider	SBM13FAC2KW006137	

Pre road test		Notes / rectification
Photograph vehicle condition	☑	570S badges missing on skirts
Photograph interior	☑	
Check Bodywork for Damage	☑	
Check closures & hinges & bonnet emergency cable	☒	Passenger door hinge is cracked
Check glazing Inc Glass Roof	☑	
Check luggage compartment	☑	Old glue residue under bonnet lip
Charger with vehicle?	☒	Car is missing charger

Notes:
Vehicle paint work condition to be checked after valeting- additional polishing may be required
Corrosion on FR arch, FL arch, passenger door on inner edge, drivers door outer and inner edges, RR arch

Road test			Notes / rectification
Check all drive modes		☑	
Check Seat Belt Operation		☑	
Check Seat Functions		☒	Seat bolsters unclipped
Check Operation of Controls and Switches & iris		☑	
Check Hand Brake and Foot Brake Travel		☑	
Check Hvac operation		☒	AC not cold
Radio working?		☑	
Check Warning Lamp Indicators		☑	
Check washers/wipers & horn		☑	
Oil level:	OK		
Check TPMS		☑	
Battery %	100		
Check mirror functions		☑	
Check exterior lighting		☑	
Check park brake function		☑	
Advise on wheel alignment feel		☑	

Notes:
Squeaks and clunks from roof seal
Wind noise from drivers window

Workshop		Notes / rectification
Check Power steering fluid	☑	
Check brake fluid	☑	
Check engine bay	☑	
Check for Bodywork Corrosion	☒	Corrosion information- see pre road test notes
Check front lights & reflectors	☑	
Check rear lights & reflectors	☑	

THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570S-Spider	SBM13FAC2KW006137	

Vehicle on lift (half height)		Notes / rectification
Check Tyre Tread & condition	☑	

Measurement	NSF	OSF	NSR	OSR
Pads (mm)	9.6mm	9.2mm	8.7mm	8.3mm
Discs (mm)				
Tyre Depth	5.3/5.7/6.3mm	5.8/6.6/5.8mm	4.3/5.6/4.9mm	5.9/6.1/6.1mm
Tyre pressure	32.1psi	29.5psi	32.3psi	31psi
Tyre Age	2023	2023	2023	2023

Turn front wheels & check Upper arms/suspension	☒	FR upper arm forward bush split, FL upper arm forward bush slight cracking
Check Front Brakes	☒	FR disc has small chip on face
Check Rim Condition	☑	
Check Rear Brakes	☑	
Check Park brake Pads	☑	

Vehicle on lift (full height)		Notes / rectification
Check Front Floor & Tyre spoilers	☑	Front floor has scuffs and scrapes
Check guide vanes	☑	
Check brake ducts	☑	
Check LTR pipes	☑	Dried coolant residue on LH LTR pipe
Check Front Suspension Ball joints & bushes	☒	Both front upper ball joint boots unseated- ball joint clips rusty. Both front lower arm forward bushes split on external rubber
Check Steering Joints/Bushes/Gaitors	☑	Both front track rods and drop links rusty
Check Front shocks & Springs	☒	Both front shock lift banjo bolts rusty. FL shock leaking
Check Front Flexible Brake Hoses	☒	Front brake unions are starting to rust
Check for leaks - oil systems	☑	
Check gearbox for leaks	☑	
Check cooling systems for leaks	☑	Old coolant residue on water pump
Check engine mounts	☑	Slight play in all engine mounts
Check manifolds	☒	LH exhaust manifold heatshield tab cracked
Check Vacuum pipes	☑	
Check Drive Shafts & seals	☑	
Check rear suspension ball Joints & Bushes	☑	
Check Rear shocks & Springs	☒	RL spring rusty at base
Check Rear brake ducts	☑	
Check Rear Flexible Brake Hoses	☑	
Check bar links & Link rods	☒	Rear track rods starting to rust
Check radiators	☑	
Under side damage	☑	

Notes: