THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	12C-Coupe	SBM11AAC6CW001145	

Pre road test		Notes / rectification
Photograph vehicle condition	☑	
Photograph interior	☑	
Check Bodywork for Damage	☒	Small scuff on right hand mirror cap
Check closures & hinges & bonnet emergency cable	☑	
Check glazing Inc Glass Roof	☑	
Check luggage compartment	☑	
Charger with vehicle?	☑	

Notes:
Sun strip fitted to vehicle
Paint lift/ multiple imperfections around both side intakes
Roof is wrapped
PPF lifted on both front arches
Road rash behind all wheels

Road test			Notes / rectification
Check all drive modes		☑	
Check Seat Belt Operation		☑	
Check Seat Functions		☑	
Check Operation of Controls and Switches & iris		☑	
Check Hand Brake and Foot Brake Travel		☑	
Check Hvac operation		☑	
Radio working?		☑	
Check Warning Lamp Indicators		☑	
Check washers/wipers & horn		☒	Washer jets have poor pressure
Oil level:	OK		
Check TPMS		☑	
Battery %	100		
Check mirror functions		☑	
Check exterior lighting		☑	Left hand indicator on mirror is slightly loose
Check park brake function		☑	
Advise on wheel alignment feel		☒	Advise wheel alignment

Notes:

Workshop		Notes / rectification
Check Power steering fluid	☑	
Check brake fluid	☑	
Check engine bay	☑	
Check for Bodywork Corrosion	☒	Corrosion under bonnet, Left hand airbrake ram mount
Check front lights & reflectors	☒	Mould visible in both headlights
Check rear lights & reflectors	☒	Rear right reflector is slightly loose/insecure

THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	12C-Coupe	SBM11AAC6CW001145	

Vehicle on lift (half height)		Notes / rectification
Check Tyre Tread & condition	☑	

Measurement	NSF	OSF	NSR	OSR
Pads (mm)	10.3mm	10.mm	7.8mm	8mm
Discs (mm)				
Tyre Depth	5.7/7/7.1mm	6.1/7.1/7.1mm	6.7/6.7/6.6mm	6.4/6.8/6.7mm
Tyre pressure	24.4psi	23.8psi	28.8psi	29.2psi
Tyre Age	2022	2022	2021	2020

Turn front wheels & check Upper arms/suspension	☑	
Check Front Brakes	☑	
Check Rim Condition	☑	
Check Rear Brakes	☑	
Check Park brake Pads	☑	

Vehicle on lift (full height)		Notes / rectification
Check Front Floor & Tyre spoilers	☒	Scuff/scrapes to underside of front bumper. Front floor is also damaged. (see photos) Tyre spoilers are also missing fixings
Check guide vanes	☒	Both guide vanes are broken
Check brake ducts	☑	
Check LTR pipes	☑	
Check Front Suspension Ball joints & bushes	☑	
Check Steering Joints/Bushes/Gaitors	☑	
Check Front shocks & Springs	☒	Front right hand spring is rusty
Check Front Flexible Brake Hoses	☑	
Check for leaks - oil systems	☒	Oil tank sump bung is greasy
Check gearbox for leaks	☑	
Check cooling systems for leaks	☑	Left hand main coolant pipe chafing
Check engine mounts	☒	All engine mounts squeaking
Check manifolds	☑	
Check Vacuum pipes	☑	
Check Drive Shafts & seals	☑	
Check rear suspension ball Joints & Bushes	☑	
Check Rear shocks & Springs	☑	Rear left spring slight rust bubbling. Residue found on rear right shock
Check Rear brake ducts	☑	
Check Rear Flexible Brake Hoses	☑	
Check bar links & Link rods	☑	
Check radiators	☑	
Under side damage	☒	Left hand skirt scuffed

Notes:
Diffuser is poorly wrapped
PPF on front bumper is bubbling as well as peeling off
Front right hand door seal trim is hanging down
PPF is lifting on both front arches
Front left Power steering fluid line covered in oily residue
Front left datum plug from underside of vehicle is missing