THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570-GT	SBM13GACXHW003288	

Pre road test		Notes / rectification
Photograph vehicle condition	☑	
Photograph interior	☑	
Check Bodywork for Damage	☑	
Check closures & hinges & bonnet emergency cable	☒	Passenger door hinge is cracked
Check glazing Inc Glass Roof	☑	
Check luggage compartment	☑	
Charger with vehicle?	☒	Car is missing charger

Notes:
One key found not working, new battery tested
Both cheater panel trims have lifted/ moved from original position

Road test		Notes / rectification
Check all drive modes	☑	
Check Seat Belt Operation	☑	
Check Seat Functions	☒	
Check Operation of Controls and Switches & iris	☑	
Check Hand Brake and Foot Brake Travel	☑	
Check Hvac operation	☑	
Radio working?	☑	
Check Warning Lamp Indicators	☑	
Check washers/wipers & horn	☑	
Oil level:	OK	
Check TPMS	☑	
Battery %	100	
Check mirror functions	☑	
Check exterior lighting	☑	
Check park brake function	☑	
Advise on wheel alignment feel	☑	

Notes:

Workshop		Notes / rectification
Check Power steering fluid	☑	
Check brake fluid	☑	
Check engine bay	☑	
Check for Bodywork Corrosion	☒	Corrosion on FR arch, passenger door, underneath front bonnet and inside drivers door.
Check front lights & reflectors	☑	
Check rear lights & reflectors	☑	

THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570-GT	SBM13GACXHW003288	

Vehicle on lift (half height)		Notes / rectification
Check Tyre Tread & condition	☒	Rear tyre tread starting to get low

Measurement	NSF	OSF	NSR	OSR
Pads (mm)	10.2mm	9.7mm	8.1mm`	8mm
Discs (mm)				
Tyre Depth	5.1/5.5/5.8mm	5.7/5.7/5.9mm	5.3/5.4/3.2mm	2.9/2.8/2.8mm
Tyre pressure	27.3psi	25.2psi	28.9psi	29.psi
Tyre Age	2021	2022	2022	2021

Turn front wheels & check Upper arms/suspension	☑	
Check Front Brakes	☑	
Check Rim Condition	☒	Paint found on FR wheel
Check Rear Brakes	☑	
Check Park brake Pads	☑	

Vehicle on lift (full height)		Notes / rectification
Check Front Floor & Tyre spoilers	☒	RH Tyre spoiler loose, front floor also has scuffs/scrapes (underside)
Check guide vanes	☑	
Check brake ducts	☑	
Check LTR pipes	☑	
Check Front Suspension Ball joints & bushes	☑	
Check Steering Joints/Bushes/Gaitors	☑	
Check Front shocks & Springs	☑	Greasy residue on FL shock, since cleaned however needs monitoring. replacement required if found in future.
Check Front Flexible Brake Hoses	☑	
Check for leaks - oil systems	☑	
Check gearbox for leaks	☑	
Check cooling systems for leaks	☑	Dried coolant residue found on Y piece
Check engine mounts	☑	Slight play in engine mounts
Check manifolds	☑	
Check Vacuum pipes	☑	
Check Drive Shafts & seals	☑	
Check rear suspension ball Joints & Bushes	☒	Rear lower arm rear bush slight cracking
Check Rear shocks & Springs	☑	
Check Rear brake ducts	☑	
Check Rear Flexible Brake Hoses	☑	
Check bar links & Link rods	☑	
Check radiators	☑	
Under side damage	☑	

Notes: