THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	12C-Coupe	SBM11AAC8CW001518	

Pre road test		Notes / rectification
Photograph vehicle condition	☑	
Photograph interior	☑	
Check Bodywork for Damage	☑	
Check closures & hinges & bonnet emergency cable	☑	
Check glazing Inc Glass Roof	☑	
Check luggage compartment	☑	
Charger with vehicle?	☑	

Notes:
Drivers door leading edge paint chipped
Passenger door arch seal hanging down

Road test		Notes / rectification
Check all drive modes	☑	
Check Seat Belt Operation	☑	
Check Seat Functions	☒	Drivers seat missing buttons
Check Operation of Controls and Switches & iris	☑	
Check Hand Brake and Foot Brake Travel	☑	
Check Hvac operation	☒	AC not cold (4 bar of pressure)
Radio working?	☑	
Check Warning Lamp Indicators	☑	
Check washers/wipers & horn	☒	1/3 screen washers blocked
Oil level:	OK	
Check TPMS	☑	
Battery %	100	
Check mirror functions	☑	
Check exterior lighting	☑	
Check park brake function	☑	
Advise on wheel alignment feel	☒	Advise wheel alignment, steering wheel off centre, front wheel vibration

Notes:

Workshop		Notes / rectification
Check Power steering fluid	☑	
Check brake fluid	☑	
Check engine bay	☑	
Check for Bodywork Corrosion	☑	
Check front lights & reflectors	☑	
Check rear lights & reflectors	☒	Slight condensation in central airbrake light

THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	12C-Coupe	SBM11AAC8CW001518	

Vehicle on lift (half height)		Notes / rectification
Check Tyre Tread & condition	☑	

Measurement	NSF	OSF	NSR	OSR
Pads (mm)	10.4mm	9.9mm	6.8mm	6.7mm
Discs (mm)				
Tyre Depth	4.8/5.9/4.2mm	4.1/4.5/4.5mm	7.1/7.2/7.2mm	3.5/5.3/6.3mm
Tyre pressure	26psi	26.9psi	29.8psi	30.2psi
Tyre Age	2019	2019	2022	2022

Turn front wheels & check Upper arms/suspension	☐	FL lower arm bushes split,
Check Front Brakes	☒	Brake disc holes blocked
Check Rim Condition	☑	
Check Rear Brakes	☒	Brake disc holes blocked
Check Park brake Pads	☒	Park brake pads crumbling

Vehicle on lift (full height)		Notes / rectification
Check Front Floor & Tyre spoilers	☒	Front floor has scuffs and scrapes, no tyre spoilers fitted
Check guide vanes	☒	Both guide vanes broken
Check brake ducts	☑	
Check LTR pipes	☑	
Check Front Suspension Ball joints & bushes	☑	
Check Steering Joints/Bushes/Gaitors	☑	
Check Front shocks & Springs	☑	
Check Front Flexible Brake Hoses	☑	
Check for leaks - oil systems	☒	Upper oil pipe braid cracked
Check gearbox for leaks	☑	Gearbox had old greasy residue around base
Check cooling systems for leaks	☑	Old coolant residue on both main coolant pipes
Check engine mounts	☑	Slight play in all engine mounts
Check manifolds	☑	
Check Vacuum pipes	☑	
Check Drive Shafts & seals	☒	LH drive shaft rusty
Check rear suspension ball Joints & Bushes	☒	Advise replace lower arm bushes cracking (no play)
Check Rear shocks & Springs	☒	RR shock is damp at base
Check Rear brake ducts	☑	
Check Rear Flexible Brake Hoses	☑	
Check bar links & Link rods	☒	Rear track rods rusty
Check radiators	☑	
Under side damage	☑	

Notes:
RH heatshield bolt missing