THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570-GT	SBM13GAC1JW004836	

Pre road test		Notes / rectification
Photograph vehicle condition	☑	
Photograph interior	☑	
Check Bodywork for Damage	☑	
Check closures & hinges & bonnet emergency cable	☒	Both door hinges cracked
Check glazing Inc Glass Roof	☑	
Check luggage compartment	☑	
Charger with vehicle?	☑	

Notes:
PPF bubble under bonnet
PPF bubble on passenger door (upper)
RR side bezel loose (squeaking)
Drivers side door 570GT badge is missing number 7
Drivers window trim loose and corroded
Passenger side door door PPF bubble towards front end

Road test		Notes / rectification
Check all drive modes	☑	
Check Seat Belt Operation	☑	
Check Seat Functions	☑	
Check Operation of Controls and Switches & iris	☑	
Check Hand Brake and Foot Brake Travel	☑	
Check Hvac operation	☒	AC not cold, 2.4 bar of pressure
Radio working?	☑	
Check Warning Lamp Indicators	☑	
Check washers/wipers & horn	☑	
Oil level:	OK	
Check TPMS	☑	
Battery %	100	
Check mirror functions	☑	
Check exterior lighting	☑	
Check park brake function	☑	
Advise on wheel alignment feel	☒	Advise wheel alignment

Notes:
Knock from front left on bumps

Workshop		Notes / rectification
Check Power steering fluid	☑	
Check brake fluid	☑	
Check engine bay	☑	
Check for Bodywork Corrosion	☒	Corrosion on both rear arches and quarters near cant rails, corrosion under bonnet, corrosion starting on both front arches, corrosion on drivers door (outer)
Check front lights & reflectors	☑	
Check rear lights & reflectors	☑	

THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	570-GT	SBM13GAC1JW004836	

Vehicle on lift (half height)		Notes / rectification
Check Tyre Tread & condition	☒	Rear tyre tread starting to get low

Measurement	NSF	OSF	NSR	OSR
Pads (mm)	7.4mm	8.3mm	7.5mm	8.4mm
Discs (mm)				
Tyre Depth	5.8/5.9/4.8mm	4.2/5.9/6.4mm	3/3/2.7mm	2.5/2.8/2.1mm
Tyre pressure	26.8psi	26.4psi	29.6psi	29.5psi
Tyre Age	2022	2022	2023	2023

Turn front wheels & check Upper arms/suspension	☒	FR upper arm forward bush cracked
Check Front Brakes	☑	
Check Rim Condition	☒	Minor damage to RR alloy, damage to FR wheel and tyre rim protector, all wheels have cosmetic damage (curb rash/chips)
Check Rear Brakes	☑	
Check Park brake Pads	☑	

Vehicle on lift (full height)		Notes / rectification
Check Front Floor & Tyre spoilers	☑	Front floor/ splitter is has scuffs and scrapes
Check guide vanes	☑	
Check brake ducts	☑	FL brake duct missing zip tie
Check LTR pipes	☑	Old dry coolant on FR LTR pipe
Check Front Suspension Ball joints & bushes	☒	All front lower bushes cracking
Check Steering Joints/Bushes/Gaitors	☑	
Check Front shocks & Springs	☑	FL shock leaking- replacement covered under TMS warranty
Check Front Flexible Brake Hoses	☐	All brake unions starting to rust
Check for leaks - oil systems	☑	
Check gearbox for leaks	☑	
Check cooling systems for leaks	☑	
Check engine mounts	☒	Play in all engine mounts
Check manifolds	☒	LH exhaust manifold heatshield tab cracked, RH rear exhaust heatshield is rattling
Check Vacuum pipes	☑	
Check Drive Shafts & seals	☑	
Check rear suspension ball Joints & Bushes	☒	Rear lower arm rear bushes cracking, rear upper arm forward bushes very slight cracking
Check Rear shocks & Springs	☑	
Check Rear brake ducts	☑	
Check Rear Flexible Brake Hoses	☒	
Check bar links & Link rods	☑	
Check radiators	☑	
Under side damage	☑	

Notes: