THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	12C-Coupe	SBM11AAC3CW000079	

Pre road test		Notes / rectification
Photograph vehicle condition	☑	
Photograph interior	☑	
Check Bodywork for Damage	☒	Side air intakes and doors have stone chips, bodywork also has lots of tar/ contamination on panels
Check closures & hinges & bonnet emergency cable	☑	
Check glazing Inc Glass Roof	☑	
Check luggage compartment	☑	
Charger with vehicle?	☑	

Notes:
Both front arches have corrosion, slight corrosion under bonnet lip, corrosion on wiper arm, slight corrosion on LH airbrake ram
RL quarter has paint peel
RH side has small scuff
PPF peel from rear bumper, LH rear quarter and LH bottom skirt
Front McLaren badge peeling
Both door leading edge trims loose

Road test		Notes / rectification
Check all drive modes	☑	
Check Seat Belt Operation	☑	
Check Seat Functions	☑	
Check Operation of Controls and Switches & iris	☑	
Check Hand Brake and Foot Brake Travel	☑	
Check Hvac operation	☑	
Radio working?	☑	
Check Warning Lamp Indicators	☑	
Check washers/wipers & horn	☑	
Oil level:	OK	
Check TPMS	☑	
Battery %	100	
Check mirror functions	☑	
Check exterior lighting	☑	
Check park brake function	☑	
Advise on wheel alignment feel	☑	

Notes:

Workshop		Notes / rectification
Check Power steering fluid	☑	
Check brake fluid	☑	
Check engine bay	☑	
Check for Bodywork Corrosion	☒	See pre road test notes
Check front lights & reflectors	☑	
Check rear lights & reflectors	☑	

THORNEY MOTORSPORT
McLAREN INDEPENDENT SPECIALIST

Multi-Point Inspection Check List

Tick: Good | Cross: Bad | Empty: Not checked

Registration	Model	Chassis Number	Mileage
	12C-Coupe	SBM11AAC3CW000079	

Vehicle on lift (half height)		Notes / rectification
Check Tyre Tread & condition	☑	Front tyre pressures low all round, since rectified

Measurement	NSF	OSF	NSR	OSR
Pads (mm)	9.5mm	7.8mm	9.8mm	9.6mm
Discs (mm)				
Tyre Depth	6.7/6.8/7mm	7/7.2/7.3mm	4.1/5.9/6mm	6/6.1/5.8mm
Tyre pressure	28psi	26.8psi	29.8psi	29.5psi
Tyre Age	2015	2015	2016	2015

Turn front wheels & check Upper arms/suspension	☑	
Check Front Brakes	☑	
Check Rim Condition	☒	Centre caps damaged, both front wheels slightly damaged, both rear wheels have lacquer peel and small chips
Check Rear Brakes	☒	RR disc has small score line (cosmetic damage only)
Check Park brake Pads	☑	

Vehicle on lift (full height)		Notes / rectification
Check Front Floor & Tyre spoilers	☒	Front floor/ bumper is heavily scuffed and scratched
Check guide vanes	☑	Front and rear guide vanes broken
Check brake ducts	☑	
Check LTR pipes	☑	
Check Front Suspension Ball joints & bushes	☑	
Check Steering Joints/Bushes/Gaitors	☑	Track rod boot greasy
Check Front shocks & Springs	☑	
Check Front Flexible Brake Hoses	☑	
Check for leaks - oil systems	☑	
Check gearbox for leaks	☑	
Check cooling systems for leaks	☑	
Check engine mounts	☑	
Check manifolds	☑	
Check Vacuum pipes	☑	
Check Drive Shafts & seals	☑	
Check rear suspension ball Joints & Bushes	☒	RL wheel has play (diagnosed to be lower arm)
Check Rear shocks & Springs	☑	
Check Rear brake ducts	☑	
Check Rear Flexible Brake Hoses	☑	
Check bar links & Link rods	☒	Inner track rod end boot split, cable tied
Check radiators	☑	
Under side damage	☒	Diffuser has sections missing/ cut out, Road rash on RH skirt (underside

Notes:
Black felt on bulk head is peeling
RH turbo elbow greasy
Road rash on rear bumper behind wheel